

3 DEC 65

S E C R E T

Idia

RS

cc

DFA

MD

INTEL

DDISA

ROUTINE

DIRECTOR

25X1A

TOR 2338Z 3 DEC 65

0501-20

IN 75498

IDEALIST LOGS

INVESTIGATION OF THE VARIOUS REPORTED A/P PROBLEMS AND THE 1332 ACCIDENT HAS RESULTED IN THE DETERMINATION THAT FAILURE TRENDS CANNOT BE SUFFICIENTLY ANALYZED FROM THE SMALL AMOUNT OF INFORMATION AVAILABLE RELATIVE TO EACH INDIVIDUAL OCCURRENCE.

EFFECTIVE IMMEDIATELY, REQUEST ALL AFCS-AHRS VENDOR REPS SUBMIT A WEEKLY REPORT BY MSG TO [] DEFINING:

25X1A

1. DRIVER SQUAWK
2. AFCS-AHRS FIELD REP ANALYSIS
3. CORRECTIVE ACTION TAKEN AND MAGNITUDE OF THE FIX, I.E., GAIN INCREASED FROM (?) VOLTS TO (?) VOLTS.
4. S/N OF DEFECTIVE COMPONENTS
5. ELAPSED TIME
6. S/N AND ELAPSED TIME FOR ANY REPLACEMENT UNIT AT TIME OF INSTL.

END OF MESSAGE

S E C R E T

